

03-10-08 10/625979

o.c.f.c

HARNES D
DICKY

MAKE-A-RECORD



March 7, 2008

Express Mail Label
No. EM 184 987 022US

Commissioner for Patents
Mail Stop Issue Fee
Alexandria, VA 22313-1450

Re: U.S. Patent No. 7,313,923
Issued January 1, 2008
For: Compressor Diagnostic System for Communicating
with an Intelligent Device
Nagaraj Jayanth et al, Inventor

Dear Sir:

We have noted, in proofreading the above-identified patent, the following typographical errors:

- Column 4, line 16, "is" should be -- its --.
- Column 6, line 11, "analyses" should be -- analyzes --.
- Column 7, line 36, "shortened" should be -- shorted --.
- Column 7, line 42, "shortened" should be -- shorted --.
- Column 8, line 57, "shortened" should be -- shorted --.
- Column 8, line 63, "shortened" should be -- shorted --.
- Column 10, line 52, "analyses" should be -- analyzes --.

EM 184 987 022 US

Harness, Dickey & Pierce, P.L.C.
Attorneys and Counselors
P.O. Box 828
Bloomfield Hills, Michigan 48303 U.S.A.
248.641.1600 • fax 248.641.0270

FOR COURIER DELIVERY ONLY
5445 Corporate Drive, Suite 200
Troy, Michigan 48098 U.S.A.

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.


www.hdp.com

Column 13, line 31, after "**shown**" delete "**in**".

Column 13, line 43, "**compressure**" should be – **compressor** --.

Kindly make these errors of record in your files.

Very truly yours,

By 

Michael Malinzak
Registration No. 43770
Attorney for Applicant

MM/d
0315-000510/COC